



No. 1009.01



Instrument Service, Inc.
3160 W. Fair Avenue
Lancaster, OH 43130
Phone: (740) 654-0500
FAX: (740) 654-3899
www.accheckinstrument.com


Certificate of Calibration

Company:
Address:
City/State:
Type Of Gage: Gage Block Accessories
Report No.: 75732
Brand: Mitutoyo
Grade: N/A
Mtl: Steel
Serial No.: 0200042/GBS-0003
Date: 11/16/2004
Invoice #: 31568
SCP#: 56

These gages were measured by comparison to a set of master blocks S/N: MSR-2, calibrated on 01/15/2004, due on 01/15/2005, and traceable to the National Institute of Standards and Technology through NIST Test No. 04-22004-A. Environmental Conditions at the time of calibration; Temperature: 68.0F. Pressure: N/A Humidity: 26.4%

Serial #	Nom. (mm)	+Tol (um)	-Tol (um)	Abs. (mm)	Dev. (um)	Comments
010036	12.00	50.00	50.00	12.00032	0.320	
010007	12.00	50.00	50.00	11.99918	-0.820	
010106	35.00	500.00	500.00	35.00005	0.050	

The undersigned certifies that the above data is a true and accurate representation of the conditions and results of the calibration performed.

Inspected By: John Kinsey  Lab Technician
Comments: N/A

- * = Out of tolerance
- S = Scratched
- B = Brinelled
- R = Rust
- C = Chipped
- D = Damaged
- T = Tapered

*** Your suggested recalibration date: 11/16/2005

*** Any number of factors may cause the calibration item to drift out of calibration before the calibration interval has expired.